

Amendments to the Drawings

Figures 1 and 2 have been amended to properly number all the elements of the present invention and to correct an inadvertent error in the orientation of the friction liner 10. The projections 24 of the liner 10 now face the projections 22 of the stator 14. No new matter is introduced to the specification, as the orientation of the projections 22, 24 was correctly described at page 5, lines 9-12 in the specification as originally filed. The replacement figures are attached herewith.